3/.

GUIDELINES FOR DECONTAMINATION OF FACILITIES AND EQUIPMENT

PRIOR TO RELEASE FOR UNRESTRICTED USE

OR TERMINATION OF LICENSES FOR BYPRODUCT, SOURCE,

OR SPECIAL NUCLEAR MATERIAL

U.S. Nuclear Regulatory Commission Division of Fuel Cycle and Material Safety Washington, D. C. 20555

أنعت المراجب والمحتورية الهيانيين والميرات بماجها

June 1980

The instructions in this guide in conjunction with Table 1 specify the radionuclides and radiation exposure rate limits which should be used in decontamination and survey of surfaces or premises and equipment prior to abandonment or release for unrestricted use. The limits in Table 1 do not apply to premises, equipment, or scrap containing induced radioactivity for which the radiological considerations pertinent to their use may be different. The release of such facilities or items from regulatory control are considered on a case-by-case basis.

- The licensee shall make a reasonable effort to eliminate residual contamination.
- 2. Radioactivity on equipment or surfaces shall not be covered by paint, plating, or other covering material unless contamination levels. as determined by a survey and documented, are below the limits specified in Table 1 prior to the application of the covering. A reasonable effort must be made to minimize the contamination prior to use of any covering.
- 3. The radioactivity on the interior surfaces of pipes, drain lines, or ductwork shall be determined by making measurements at allies traps, and other appropriate access points, provided that contamination at these locations is likely to be representative of contamination on the interior of the pipes, drain lines, or ductwork. Surfaces of premises, equipment, or scrap which are likely to be contaminated but are of such size, construction, or location as to make the surface inaccessible for purposes of measurement shall be presumed to be contaminated in excess of the limits.
- 4. Upon request, the Commission may authorize a licensee to relinquish possession or control of premises, equipment, or scrap having surfaces contaminated with materials in excess of the limits specified. This may include, but would not be limited to, special circumstances such as razing of buildings, transfer of premises to another organization continuing work with radioactive materials, or conversion of facilities to a long-term storage or standby status. Such requests must:
 - a. Provide detailed, specific information describing the premises, equipment or scrap, radioactive contaminants, and the nature, extent, and degree of residual surface contamination.
 - b. Provide a detailed health and safety analysis which reflects that the residual amounts of materials on surface areas, together with other considerations such as prospective use of the premises, equipment or scrap, are unlikely to result in an unreasonable risk to the health and safety of the public.

- 5. Prior to release of premises for unrestricted use, the licensee shall make a comprehensive radiation survey which establishes that contamination is within the limits specified in Table 1. A copy of the survey report shall, be filed with the Chief, Material Licensing Branch, Division of Fuel Cycle and Material Safety, USNRC, Washington, D.C. 20555, and also the Director of the Regional Office of the Office of Inspection and Enforcement, USNRC, having jurisdiction. The report should be filed at least 30 days prior to the planned date of abandonment. The survey report shall:
 - Identify the premises.
 - b. Show that reasonable effort has been made to eliminate residual contamination.
 - c. Describe the scope of the survey and general procedures followed.
 - d. State the findings of the survey in units specified in the instruction.

Following review of the report, the NRC will consider visiting the facilities to confirm the survey.

TABLE I
ACCEPTABLE SURFACE CONTAMINATION LEVELS

NUCL IDES a	AVERAGE ^D C f	HAXIIINH p q t	REHOVABLE D e 1
J-nat, U-235, U-238, and issociated decay products	5,000 dpm ₂ /100 cm ²	15,000 dpm a/100 cm²	
ransuranićs, Ra-226, Ra-228, 1-230, Th-228, Pa-231, C-227, 1-125, 1-129	100 dpm/100 cm²	300 dpm/100 cm ²	1,000 dpm a/100 cm ²
h-nat, Th-232, Sr-90, a-223, Ra-224, U-232, I-126, -1J1, I-1J3	1000 dpm/100 cm²	3000 dpm/100 cm ²	200 dpm/100 cm ²
eta-garma enitters (nuclides ith decay modes other than lpha amission or spontaneous ission) except SR-90 and thers noted above.	5000 dpin ay/100 cm²	13,000 dpm 3y/100 cm²	1000 dpm 3y/100 cm ²

alflure surface contamination by both alpha- and beta-gamma-emitting nuclides exists, the limits established for alpha- and beta-gamma-cmitting nuclides should apply independently.

. . *

As used in this table, dpm (disintegrations per minute) means the rate of emission by radioactive material as determined by correcting the counts per minute observed by an appropriate detector for background, efficiency, and geometric factors associated with the instrumentation.

Hensurements of average contaminant should not be averaged over more than 1 square meter. For objects of less surface

The maximum contamination level applies to an area of not more than 100 $\rm cm^2$.

The amount of removable radioactive material per 100 cm² of surface area should be determined by wiping that area with dry filter or soft absorbent paper, applying moderate pressure, and asset sing the amount of radioactive material on the ulpe with an appropriate instrument of known efficiency. When removable contamination on objects of less surface area is determined, the pertinent revels should be reduced proportionally and the entire surface should be wiped.

The average and maximum radiation levels associated with surfice contamination resulting from beta-gamma emitters should no exceed 0.2 mond/hr at) cm and 1.0 mond/hr at) cm, is pectively, measured through not more than 7 milligrams per square